

Logic Air STC List

#	STC / LSTC	Title	Aircraft Type	Type Certificate
1	C-LSA98-003/D	Installation, dual UNS-1M Navigation Management ...	Lockheed-1011-385-1	A-127
2	PDA05-3	Installation of the Corporation Logic Air Cable Asse...	Airbus A310	A-205
3	C-LSA12-003/D	Installation of JANITROL combustion Heater System ...	Hawker Siddeley HS 748	A-87
4	SA07-12 ST02385NY EASA.I...	Tire Pressure Indication System De-Activation	Boeing 767-306/328	A-137
5	C-LSA11-015/D	Installation of Dual CMC GPS Landing System (GLS) ...	Boeing 737-36Q	A-146
6	Q-LSA05-019/D	Galley Modification	Boeing 767-306	A-137
7	C-LSA12-020/D	Introduction of Roll Steering Interface to Dual GNX-...	Hawker Siddeley HS 125 Series 700A	A-75
8	C-LSA12-021/D	Re-Configuration, FWD and AFT Galley Ovens	Airbus A330-243	A-205
9	C-LSA04-023/D	Passenger Entertainment System Modification	Airbus A310-304	A-151
10	C-LSA06-031/D	Installation, 270 Passenger Interior Configuration	Boeing 767-306	A-137
11	C-LSA07-031/D	Installation of Honeywell KLN 900 GPS System	SAAB SF340A	A-195
12	SA19-31	Installation of GNSS with LPV Approach / ADS-B Sys...	Boeing 737-600,-700,-800 Series	A-146
13	C-LSA06-033/D	Installation, Inflight Entertainment System	Boeing 767-306	A-137
14	Q-LSA18-036/D EASA 10067...	Removal of the LDMCR and Installation of Lavatorii...	A330-243	A-205
15	C-LSA19-036/D	Cabin OHSC Reconfiguration, Cabinet and Partition I...	Airbus A330-243	A-205
16	C-LSA15-039/D	Installation, Honeywell KLN-900 GPS System	SAAB 340B	A-195
17	C-LSA13-043/D	Cabin Modification to Support Passenger Seating Ar...	Airbus A330-342	A-205

#	STC / LSTC	Title	Aircraft Type	Type Certificate
18	C-LSA14-048/D	Cabin Modification to Support Passenger Seating Ar...	Airbus A330-243	A-205
19	C-LSA95-052/D	Installation, dual UNS-1M Navigation Management ...	Lockheed-1011-385-1	A-127
20	C-LSA13-053/D	Cabin Modification to Support Passenger Seating Ar...	A310-304/308	A-151
21	SA05-55	Deviation From FAA STC ST00705SE, Installation of H...	Boeing 747-121/123/128/129/133/1D1/211B/212B/21...	A-127
22	C-LSA05-055/D	Deviation From FAA STC ST09367SC, Installation of ...	Douglas DC-9-83 (MD-83)	A-160
23	C-LSA06-059/D	Installation, Honeywell KLN-900 GPS System	SAAB SF340A	A-195
24	C-LSA17-070/D	Installation, Modification to Support Cabin Reconfig...	Airbus A330-243	A-205
25	C-LSA12-079/D	Cabin Modification to Support Passenger Seating Ar...	Airbus 330-243	A-205
26	SA15-84 ST03874NY EASA 1...	Installation of Second Flight Management Computer	Boeing 737-300/400/500 Series	A-146
27	C-LSA97-089/D	Modification of TCAS II Traffic Display Configuration	Lockheed-1011-385-3	A-127
28	C-LSA18-089/D	Seat track Installation	Airbus 330-243	A-205
29	C-LSA07-091/D ST02463NY ...	Installation of Mode S ATC Transponder with Elemen...	Boeing 767-306 & 328	A-137
30	SA11-92 EASA.10043626 ST0...	Dual CMC SBAS Landing System	Boeing 737-300/400/500 Series	A-146
31	C-LSA14-094/D	Installation of Flightdeck Door lock Indication System	Bombardier DHC-8-402	A-142
32	C-LSA04-095/D	FWD Cabin Modification	Boeing 767-328	A-137
33	C-LSA13-102/D	Cabin Modification to Support Passenger Seating Ar...	Airbus A330-243	A-205
34	C-LSA11-105/D	Installation of In-Flight Entertainment System	Boeing 737-36Q/36N	A-146
35	C-LSA12-107/D	Installation of Rockwell Collins Airshow 420 Passeng...	Airbus 330-243	A-146

#	STC / LSTC	Title	Aircraft Type	Type Certificate
36	C-LSA11-108/D	Alternative Mounting Arrangement for Seat Electron...	Airbus 330-342	A-205
37	C-LSA08-110/D	Installation of 202 Passenger Interior Configuration	Boeing 757-28A	A-161
38	C-LSA12-111/D	Cabin Modification to Support Passenger Seating Ar...	Airbus 330-243	A-205
39	C-LSA08-112/D	Installation, Heads-Up Technologies PBS-600 Cabin ...	Boeing 767-306/328	A-137
40	C-LSA97-115/D	Installation, Aux UNS-1M Navigation Management S...	L1011-385-1	A-127
41	C-LSA97-118/D	Activation, Collins TCAS II / Mode-S Transponder	Airbus 310-300	A-151
42	C-LSA08-118/D	Installation, Heads-Up Technologies PBS-600 Cabin ...	Boeing 757-28A	A-161
43	C-LSA05-119/D	Installation, 270 Passenger Interior Configuration	Boeing 767-306	A-137
44	C-LSA16-121/D	Installation UNS-1EW Flight Management System	Bombardier DHC-8-311	A-142
45	C-LSA05-123/D	Installation, Dual UNS-1E Flight Management Syste...	Bombardier DHC-8-311	A-142
46	C-LSA05-124/D	Installation of ICS-100 Iridium Satellite Communicati...	Bombardier DHC-8-311	A-142
47	C-LSA17-126/D	Galley Modification	Airbus A330-243	A-205
48	C-LSA09-128/D	Installation, Dual Honeywell STAR Flight Director	Hawker Siddeley HS 748 series 2A	A-87
49	C-LSA12-129/D	Cabin Modification to Support Passenger Seating Ar...	Airbus A330-243	A-205
50	C-LSA08-130/D	Modification Galley Floor Attachement	Boeing 757-28A	A-161
51	C-LSA07-132/D	Installation, 201/205/228 Passenger Interior Configu...	Boeing 757-28A	A-161
52	C-LSA04-133/D	Installation of Flightdeck Door lock Indication System	DHC-8-402	A-142
53	C-LSA13-133/D	Installation, Honeywell KLN-900 GPS System	SAAB SF340B	A-195

#	STC / LSTC	Title	Aircraft Type	Type Certificate
54	C-LSA06-141/D	Installation of Rockwell Collins TCAS II System	Hawker Siddeley HS 125 Series 700A	A-75
55	C-LSA06-142/D	Installation of Rockwell Collins VHF-22C #2 Comm w...	Hawker Siddeley HS 125 Series 700A	A-75
56	C-LSA07-145/D	Installation of dual ACSS XS-950 Mode S Transpond...	Boeing 757-28A	A-161
57	C-LSA07-147/D	Installation of Heads-Up Technologies PBS-600 Digit...	Boeing 757-28A	A-161
58	C-LSA10-147/D	Honeywell KRA 405 Radar Altimeter Installation	Hawker Siddeley HS 748 Series 2A	A-87
59	C-LSA12-169/D ST03377NY	Installation of Second Flight Management Computer	Boeing 737-53A	A-146
60	C-LSA00-175/D	Installation of TCAS Antenna Electrical Disconnect	Boeing 757-200 Series	A-161
61	C-LSA04-186/D	Deactivation of Tire Pressure Indicating System	Boeing 767-306 & 328	A-137
62	C-LSA08-189/D	Installation of Heads-Up Technologies PBS-600 Digit...	Boeing 737-201/2X6C	A16WE
63	C-LSA07-190/D EASA. IM.A.S....	Upgrade to Honeywell Mark V EGPWS	Boeing 767-328	A-137
64	C-LSA00-195/D	Installation of Allied Signal KLN 90B GPS System	Convair 340/440 (CV580)	A-220
65	C-LSA97-200/D	Activation, Collins TCAS II System	Boeing 737-42M	A-146
66	C-LSA00-201/D	Installation of BF Goodrich AIM Artificial Horizon Ind...	Convair 440 (CV580)	6A6
67	C-LSA07-205/D ST02542NY ...	Installation, Inflight Entertainment System	Boeing 767-306/328	A-137
68	C-LSA07-210/D ST02454NY ...	Installation 270/269 Pax Interior Configuration	Boeing 767-306/328	A-137
69	C-LSA12-211/D	Cabin Modification to Support Passenger Seating Ar...	Airbus A330-342	A-205
70	C-LSA11-228/D	Galley Oven Replacement and PSM Reconfiguration	Airbus 330-243	A-205
71	C-LSA99-239/D ST01102NY	Upgrade to Allied Signal RTA-83A Tranceivers with A...	L-1011-385-1	A-127

#	STC / LSTC	Title	Aircraft Type	Type Certificate
72	C-LSA99-241/D	Upgrade to 8.33 KHz Spacing, VHF Communication ...	Boeing 757-200 Series	A-161
73	C-LSA07-241/D	Installation, Artex C406 Emergency Locator Transmit...	Boeing 737-200	A16WE
74	C-LSA99-243/D	Upgrade to Collins VHF-700B or Allied Signal RTA-8...	Airbus 310-300	A-151
75	C-LSA09-244/D	Modification to Existing In-Flight Entertainment Syst...	Airbus A330-342/343	A-205
76	C-LSA10-244/D	Interior Modification to Support Passenger Seating ...	Airbus 330-243	A-205
77	C-LSA09-247/D	Overhead Bin Installation & PSU Rearrangement	Airbus A330-342	A-205
78	C-LSA00-251/D	Installation, Passenger Entertainment System	L-1011-385-3	A-127
79	C-LSA01-259/D	Passenger Entertainment System Modification	Airbus 310-308	A-151
80	C-LSA01-260/D	Installation 259 Passenger Interior Configuration	Airbus 310-308	A-151
81	C-LSA99-264/D	Upgrade to Collins P/N 822-1044-020 VHF Commun...	Airbus 330-342	A-205
82	C-LSA10-268/D	Interior Mods to Support Seating Reconfiguration	A330-243	A-205
83	C-LSA05-278/D	Re-Location of 2-VOR Antenna P/N CI-120-1 to A/C ...	Convair 340	A-220
84	C-LSA05-279/D	Re-Location of 2-VOR Antenna P/N CI-120-1 to A/C ...	Convair 440	A-220
85	C-LSA06-287/D	Installation of Honeywell KLN 900 GPS System	SAAB SF340A	A-195
86	C-LSA01-298/D	Re-Location of 2-VOR Antenna P/N CI-120-1 to A/C ...	Convair 340/440	A-220
87	C-LSA98-303/D	Replacement of INS #3 with P/N 2583596-901 VG M...	L-1011-385-3	A-127
88	C-LSA01-303/D	Installation of Honeywell Primus 90 Weather Radar S...	Convair 440	6A6
89	C-LSA01-304/D	Installation of Honeywell KLN 900 GPS System	Convair 440	6A6

#	STC / LSTC	Title	Aircraft Type	Type Certificate
90	C-LSA09-306/D	Conversion from ACARS to ATC COMM, VHF COMM ...	Boeing 737-81Q	A-146
91	C-LSA08-308/D	Installation, Artex C406-1 Emergency Locator Trans...	Hawker Siddeley HS 748 series 2A	A-87
92	C-LSA07-315/D	Installation, Sandel Class A TAWS	Hawker Siddeley HS 748 series 2A	A-87
93	C-LSA01-337/D	Airworthiness Approval, GPS Approach Function, Ho...	Bombardier DHC-8-300	A-142
94	C-LSA02-337/D	Installation of Shadin AMS 2000 Altitude manageme...	Convair 340/440 (CV580)	A-220
95	C-LSA08-343/D	Installation of Honeywell Primus 90 Weather Radar S...	Hawker Siddeley HS 748 series 2A	A-87
96	C-LSA08-344/D	Installation, KLN 94 GPS System (IFR Enroute, Termin...	Hawker Siddeley HS 748 series 2A	A-87
97	C-LSA98-356/D	Installation of Allied Signal KLN 90B GPS System (IFR...	Convair Liner 340 (CV580)	6A6
98	C-LSA03-370/D	Changes, Cabin Seat Belt Chime Circuit	McDonnell Douglas DC-9-83	A-160
99	C-LSA05-389/D	Installation of In-Flight Entertainment System, with L...	Boeing 767-328	A-137
100	C-LSA07-403/D	Installation, UNS-1C Flight Management System	Boeing 737-201/2X6C	A16WE
101	C-LSA03-412/D	Installation of Honeywell KLN 900 GPS System	SAAB SF340A	A-195
102	C-LSA01-438/D	Installation of Universal UNC-1C Flight Management...	Bombardier DHC-8-300	A-142
103	C-LSA03-475/D	Installation of 15-inch LCD Monitor or 37-inch Plasm...	Boeing 767-328	A-137
104	C-LSA03-488/D	Installation of Video Display Monitor, FS 661	Boeing 767-328	A-137
105	C-LSA03-498/D ST02467NY ...	Changes to Altitude Callouts Configuration, Honeyw...	Boeing 767-306/328	A-137
106	ST03377NY	Installation of Second Flight Management Computer	Boeing 737-53A	A16WE
107	Q-LSA94-028	Passenger cabin interior seating reconfiguration to 3...	Lockheed L-1011-385-1-15 (TriStar)	A-127

#	STC / LSTC	Title	Aircraft Type	Type Certificate
108	C-LSA95-145/D	Galley Cart Tie-Down P/N 1593340-121, 1592936-10...	Lockheed Martin L1011	A-127
109	C-LSA95-156/D	Modification of Forward, Aft, and Lower Deck Galleys	Lockheed L1011-385-1	A-127
110	Q-LSA96-33	Reactivation of the captain's and first officer's vertica...	Lockheed Martin L-1011-385-1-15 (TriStar)	A-127
111	C-LSA96-139/D	Installation, Engine Supplement Heat	DHC-8 100 DHC-8-300	A-142
112	Q-LSA97-20	Aft Galley Single High Temperature Oven Installation.	Convair 340 (580)	6A6 (SA4-1100)
113	C-LSA98-024/D	Video Technology Services LC-Star Video Projector a...	Lockheed L 1011-385-3	A-127
114	C-LSA98-058/D	V.T.S. 10.4 Inch LCD Video Monitor Installation.	Boeing 757-236	A-161
115	C-LSA98-313/D	Removal of Collins ACARS system and Addition of si...	Airbus A310, 304	A-151
116	C-LSA98-327/D	Sundstrand DFDR Upgrade.	Boeing 737-200	A16WE
117	C-LSA98-336/D	Installation, Dual UNS-1M Navigation Management ...	Lockheed L1011-385-1	A-127
118	C-LSA99-162/D	Upgrade to Sundstrand Digital Universal Flight Data ...	Boeing 727-100	A3WE
119	C-LSA99-189/D	Upgrade of VHF Communications System to 8.33 KH...	Boeing 757-200	A-161
120	C-LSA99-209/D	Upgrade to Allied Signal p/n 064-50001-0101 VHF C...	Lockheed L-1011-385-1, L-1011-385-1-14, L-1011-385...	A-127
121	C-LSA99-271/D	Upgrade of #3 VHF Communications System to Colli...	Boeing 727-193	A3WE
122	C-LSA00-152/D	Installation of Dual Universal Avionics UNS 1M Navi...	Boeing 727-100	A3WE
123	C-LSA00-159/D	Audio Program Schedule Change, Matsushita RD-AX...	Boeing 757-200	A-161
124	C-LSA00-221/D	Instl, P/N GD-V4200PZW-G Video Monitors, Zones ...	Lockheed L1011-385-1, L1011-385-3	A-127
125	C-LSA00-236/D	Installation of SONY p/n 743-0238-001 HI-8 Video T...	Lockheed L1011-385-1	A-127

#	STC / LSTC	Title	Aircraft Type	Type Certificate
126	C-LSA01-307/D	Replacement of Cockpit Voice Recorder: United Cont...	Convair 340,440	A-220
127	C-LSA01-336/D	Pitot Heat Warning System Modification	Boeing 727-217	A-179
128	C-LSA01-418/D	Installation of single APC part number411-0001-114...	Boeing 737-200	A16AW
129	C-LSA01-442/D	Installation of Sony HI-8 Video Tape Reproducer (VTR)	Boeing 757-28A	A-161
130	C-LSA02-349/D	Installation of Half-Cart Retainers in Galleys G2, G3 a...	McDonnell Douglas DC9-83 (MD-83)	A-160
131	C-LSA03-381/D	Installation, Universal UNS-1M NMS System	McDonnell Douglas HC DC9-83	A-160
132	C-LSA04-027/D	Installation of SELL P/N 8001-06-0000 Oven in Galle...	Airbus A310-304	A-151
133	C-LSA04-139/D	Installation of additional DFDR parameters	Airbus A310-304	A-151
134	C-LSA04-424/D	Modification, Galley Electrical System	Airbus A310-304	A-151
135	C-LSA05-096/D	Installation of Replacement IFE seat Harness Assembly	Airbus A330-243	A-205
136	C-LSA05-127/D	Upgrade to Solid State Cockpit Voice Recorder	Bombardier DHC-8-311	A-142
137	C-LSA05-128/D	Upgrade to Solid State Flight Data Recorder	Bombardier DHC-8-311	A-142
138	C-LSA05-284/D ST00791NY	Installation, Dual UNS-1M Navigation Management ...	Lockheed Martin L-1011-385-3	A-127
139	C-LSA05-285/D	Instl, 269 Passenger Seating Arrangement	Lockheed L-1011-385-3	A-127
140	C-LSA05-367/D	Instl, 269 Passenger Seating Arrangement	Boeing 767-328	A-137
141	C-LSA06-143/D	Installation of KGS Inverter with power outlets	Hawker Siddeley HS.125 Series 700A	A-75
142	C-LSA06-209/D	Tire Pressure Indication System De-activation	Boeing 767-306	A-137
143	SA08-1	Installation Provisions, Iridium SATCOM / GPS S67-1...	Boeing 747-121, 747-123, 747-128, 747-129, 747-133, ...	Same as F

#	STC / LSTC	Title	Aircraft Type	Type Certificate
144	P-LSA16-011/D	APU Elapsed Time Indicator Installation	Boeing 737-300 Series, 737-400 Series, 737-500 Series	A-146
145	SA16-62	Dual GPS Installation (Structural Provisions Only)	Boeing 737-300 Series, 737-400 Series, 737-500 Series	A-146
146	P-LSA16-038/D	Structural Provisions for Dual GPS Antenna Installation	Boeing 737-33A	A-146
147	P-LSA17-054/D	A330 Closet Modification	Airbus S.A.S. A330-243	A-205
148	O-LSA21-089/D	Dual UNS-1Ew FMS Software Upgrade	De Havilland DHC-8-311	A-142
149	O-LSA22-001/D	Modification to G2 and G4B Galleys	Boeing 737-4K5, 737-408	A-142
150	C-LSA23-049/D	Interior Modification	Airbus S.A.S. A330-343	A-205
151	C-LSA23-098/D	Installation of Multi-Function Display	Boeing 737-300 Series	A-146
152	ST03339CH	Standard passenger Configurations	Boeing 767-300 series	A1NM
153	O-LSA14-086/D	IFE Harness	A330-243	A-205
154	O-LSA15-040/D	Seat Harness (Double)	A319-112/114	A-166
155	MDL 11161901 Rev. C	Seat Harness (Double)	Boeing 767-224	A1NM
156	Q-LSAP06-002/D Avianor	Modification of B/E Aerospace Passenger Seats: 990-...	N/A	N/A
157	Q-LSAP06-003/D Avianor	Modification to Jepson Burns passenger seats: 870X...	N/A	N/A
158	SA07-8 AeroMechanical Servi...	AFIRS 220 Automated Flight Information Reporting ...	Boeing 737-200/300/400/500/600/700/800 series	A16WE & A-1...
159	Q-LSAP05-020/D Avianor	Modification to B/E Aerospace Triple Seat and Doubl...	N/A	N/A
160	SA07-24 STO2258NY Lufthan...	Installation of Guideline self Illuminating	Boeing 767-200 & 300 Series	A-137
161	SA07-47 AeroMechanical Ser...	AFIRS 220 Automated Flight Information Reporting ...	Boeing 757-200 Series	A-161

#	STC / LSTC	Title	Aircraft Type	Type Certificate
162	Q-LSAP05-053/D Avianor	Modification to B/E Aerospace Passenger Seat: C011...	N/A	N/A
163	Q-LSAP04-060/D Avianor	Modification to Jepson Burns Double and Triple Seats	N/A	N/A
164	SA09-72 STC02773NY Ukrain...	Installation, Inflight Entertainment System	Boeing 767-300 Series	A-137
165	O-LSA-98-136/D Northeast E...	TCAS II Installation	Hawker Siddeley HS 748	A-87
166	O-LSA-97-140/D Northeast E...	GPS Installation	Hawker Siddeley HS 748 Series 2A	A-87
167	C-LSA10-149/D AeroMechan...	Provision ONLY for AFIRS 220 Automated Flight Info...	Bombardier DHC-8-402	A-142
168	C-LSA96-166/D Air Transat	Replacement of Dual RCA AVQ-30 Weather Radar Sy...	L-1011-385-1/-3	A-127
169	C-LSA04-185/D AllCanada Ex...	Installation of Dual Universal Avionics UNS-1C Flight...	Boeing 727-221	A-179
170	C-LSA08-199/D AeroMechan...	AFIRS Antenna Installation (Deviation from STC SA0...	Boeing 737-8AS	A-146
171	C-LSA97-304/D Royal Aviation	Installation, Trimble YNL-2100T GPS	Boeing 737-200C	A16WE
172	C-LSA07-377/D AeroMechan...	AFIRS 220 Automated Flight Information Reporting ...	Boeing 767-306/328	A-137
173	ST02723AT B/E Aerospace	Dual Antenna Structural Provisions Installation	Boeing 737-300/400/500 Series	A16WE
174	SA16-86 Kelowna Flightcraft	ADS-B OUT to meet requirements of FAA 14CFR 91....	Boeing 737-300 Series, 737-400 Series, 737-500 Series	A-146
175	C-LSA10-128/D Air North	Installation, Heads-Up Technologies PBS-600 Cabin ...	Boeing 737-400 Series, 737-500 Series	A-146
176	EASA 10075510 S4E Solution...	CMA-525 SLS Control Panels Replacement (Touch Di...	Boeing 737-300, 737-400, 737-500 Series	N/A